



# Return to Flight Status

Neil Otte



# Columbia Investigation

# Columbia Investigation Overview




***Columbia hit by  
foam lost from  
left hand bipod***

# Columbia Investigation Overview



## **Major Findings**

- ***Design verification and process validation did not encompass all material and processing variability or adequately address all failure modes***
- ***Quality Control verification of the manual spray application process did not preclude process variations affecting the part integrity***
- ***Available acceptance testing / inspection techniques were not capable of rejecting ramps with adverse “as-built” features which could threaten the TPS integrity***



***Shuttle, and therefore External Tank, must consider debris as a critical environment***

# CAIB Recommendations for External Tank



**Thermal Protection System** *R.3.2-1: Initiate an aggressive program to eliminate all External Tank Thermal Protection System debris-shedding at the source with particular emphasis on the region where the bipod struts attach to the External Tank.*

**Imaging** *R3.4-2: Provide a capability to obtain and down link high-resolution images of the ET after it separates. R3.4-3: Provide a capability to obtain and down link high-resolution images of the underside of the Orbiter wing leading edge and forward section of both wings' TPS.*


**Closeouts** *R.4.2-3: Require that at least two employees attend all final closeouts and intertank hand-spraying procedures.*

*External Tank is complying with all CAIB recommendations*

# Preliminary Debris Requirements



## ET TPS Debris Allowables for Return to Flight



# Flight History Used to Determine Areas of Redesign Necessary for Tank




**Space Shuttle Program** *Identifying Observed TPS > Level II Debris Requirement* 

• ET Imagery Review (STS-84 – STS-107) - Summary of Foam Loss Events

	LO2 Tank Acreage	LH2 Tank Acreage	Intertank Acreage (non-popcorn related events)	Bipod Ramps	LO2 to Intertank Flange	LH2 to Intertank Flange	Jack Pads	LH2 PAL Ramp	LO2 PAL Ramp
Flights with Imagery	21	23	23	21	21	23	16	14	13
Flight with TPS loss Observed	0 (0%)	8 (35%)	8 (35%)	2 (9%)	0 (0%)				
Substrate Exposed	0	0	1	1	0				
Flights with no data obtained	9	7	7	9	9				

9




***Efforts underway to address areas with known violations of new debris requirements***




# External Tank Animated Overview




# Bipod Redesign Overview



Was



Now



***We have simplified and added controls to the foam application process***



# Bipod Redesign Foam Processing



**DEVELOPMENT**

- Basic Process**
- Requirements Met
  - Equipment Specified
  - Basic Skills Developed
  - Process Enhancement Test Plan

**ENHANCEMENT**

- Refined Process**
- Variables Eliminated/ Understood
  - Variation Reduced
  - Verification Test Plan

**VERIFICATION**


- Verified / Locked Down Process**
- Parameters Verified
  - Spray Sched Defined
  - PPD/MPP Defined
  - Validation Test Plan

**VALIDATION**

- Process Demonstrated**
- Repeatability Proven
  - Part Specific Certified Personnel

**PRODUCTION**




Same Sprayers Throughout



Statistically Significant Number of Data Points


*New foam applications on bipod are far superior to pre-Columbia*

# Bipod Redesign Certification



***Bipod redesign will be fully certified***

# Bipod Redesign Status




***We have begun retrofitting External Tank***


A person wearing a white protective suit, mask, and gloves is operating a device mounted on a bipod. The scene is set in a laboratory or industrial environment with various equipment and materials visible. The overall image has a blue tint.

# Bipod Video

# Flange Foam Loss




1. LN2 begins to form in voids as LH2 level approaches flange
2. Flange temps rapidly fall to form SN2 in leak paths blocking flow
3. LN2 and SN2 begins to accumulate in Y joint during hold
4. During ascent LH2 level drops, flange temps begin to rise
5. LN2 begins to gasify causing foam to crack
6. Ascent heating weakens outer layer of foam
7. LN2 enters crack and begins rapid gasification
8. Crack rapidly propagates to substrate, conathane, flange
9. Divot produced due to weak outer layer and LN2/GN2





# Flange Redesign Required Development of Test Bed to Find Root Cause of Foam Loss



Intertank "Y-joint"  
(Warm)

Intertank "Y-joint"  
(Cryo)



***We have determined how and why the flange foam was being lost***

# Redesign Elements of the Flange



Reversed Bolts

Crew of STS-114 Examine Flange Mods

***We are addressing contributors to foam loss on the flange  
(voids and leak path)***

# Redesign Elements of the Flange



**Flange Stringer Injection**



**Upper Flange Spray**



**Thrust Panel Injection**





**Lower Flange Spray**

# Characterizing Divoting Foam Loss




Thermal Vac Test



***Our understanding of the divoting foam loss mechanism has increased dramatically and we continue to aggressively test***


# Current Status of Flange



Flange Runs Beneath Feedline



ET Vertical in Cell A

***The manufacturing flow for retrofit External Tanks is radically different than for in-line production, but we are ready to proceed***

A person wearing a white protective suit and gloves is working on a complex mechanical assembly. The assembly consists of various components, including a large cylindrical part on the left and several smaller parts on the right. The person is using a tool to work on the assembly. The background is a plain, light-colored surface. The text "Flange Video" is overlaid on the image in a large, white, sans-serif font.

# Flange Video

# Feedline Bellows




***An additional debris source was identified for elimination***


# Feedline Bellows Testing and Redesign




Lower Feedline Bellows During Baseline Test at Eglin AFB



Cutaway View of Bellows Drip Lip Configuration with Retainer





Cutaway View of Bellows Drip Lip Configuration with Nanogel and Scrim Cloth Retainer





***We have identified a two part design fix***

# Certification of the Bellows Redesign




***Bellows redesign will preclude ice and certification is in work***

# Bellows Manufacturing / Process Validation Status



Aft Bellows




Bellows Spray




PDL Pour

***ET-120 retrofit processes are being validated***





# Bellows Video

# PAL Ramp




Ten Foot Section of Removed PAL Ramp  
with Critical Area Shown in Red Box




PAL Ramp Spray

***We have removed the PAL ramp over the flange and  
are refining the process to replace it***

# Enhanced In-Flight Imaging



Camera Lens



Potential Field of View



Internal View  
of Camera  
Installation


***External Tank is supporting program imaging requirements***

# Enhanced In-Flight Imaging System




## Interface at Ground Umbilical Carrier Plate


- On / Off
- Battery Charging / Monitoring




BX-265 Closeout



Two Antennas on -Z



One Camera in LO2 Feedline Fairing




Electronics Box in Intertank



# Non-Destructive Evaluation (NDE)



Terahertz



Backscatter



***NDE is being aggressively developed but is not currently available for hardware acceptance***



***The External Tank  
will be ready to  
safely support the  
Crew of STS-114  
and missions  
to follow!***